

TREE MITIGATION						
Common Name	Height	Spread	Diameter at 4.5 ft DBH	TOTAL Points	Tree Condition Ranking	Status
Live Oak			13	66%	Fair	REMOVE
Live Oak			17	81%	Good	REMOVE
Live Oak			15	75%	Good	REMOVE
Live Oak			18	78%	Good	REMOVE
Live Oak			17	81%	Good	REMOVE
Sabal Palm				72%	Good	REMOVE
Sabal Palm				69%	Fair	REMOVE
Sabal Palm				75%	Good	REMOVE
Silver Buttonwood			9	94%	Excellent	REMAIN
Silver Buttonwood			5	91%	Excellent	REMAIN
Sabal Palm				84%	Good	REMOVE
Sabal Palm				141%	Excellent	REMOVE
Sabal Palm				91%	Excellent	REMOVE
Live Oak		48' x 45'	26	81%	Good	REMOVE
Live Oak		40' x 32'	22	78%	Good	REMOVE
Live Oak		43' x 42'	22	72%	Good	REMOVE
Sabal Palm				88%	Excellent	REMOVE
Sabal Palm				91%	Excellent	REMOVE
Sabal Palm				88%	Excellent	REMOVE
Live Oak	36' OA / 15' CLR	50' x 45'	29	75%	Good	REMOVE
Live Oak	34' OA / 16' CLR	44' x 42'	23	84%	Good	REMOVE
Sabal Palm				97%	Excellent	REMOVE
Sabal Palm				88%	Excellent	REMOVE
Live Oak	42' OA / 14' CLR	68' x 61'	32	78%	Good	REMOVE
Live Oak			12	34%	Poor	REMOVE
Sabal Palm				88%	Excellent	REMOVE
Sabal Palm				91%	Excellent	REMOVE
Sabal Palm				88%	Excellent	REMOVE
Live Oak	39' OA / 14' CLR	52' x 49'	25	78%	Good	REMOVE
Live Oak	41' OA / 15' CLR	53' x 43'	26	72%	Good	REMOVE
Australian Pine				0%	Poor	REMAIN
Common fig				0%	Poor	REMAIN
Live Oak	18' CLR	34' to Street		0%	Poor	REMAIN
Live Oak	17' CLR	35' to Street		0%	Poor	REMAIN
Live Oak	14' CLR	36' to Street		0%	Poor	REMAIN
Green Buttonwood	12' CLR		7	69%	Fair	REMAIN
Green Buttonwood	16' CLR		11	72%	Good	REMAIN
Green Buttonwood	14' CLR		15	66%	Fair	REMAIN
Green Buttonwood	17' CLR		8	72%	Good	REMAIN
Green Buttonwood	12' CLR		9	78%	Good	REMAIN
Green Buttonwood	11' CLR		11	81%	Good	REMAIN
Green Buttonwood	11' CLR		6	72%	Good	REMAIN
Live Oak	18' CLR		15	84%	Good	REMAIN
Live Oak	17' CLR		8	84%	Good	REMAIN
Live Oak	16' CLR		11	78%	Good	REMAIN
Live Oak	14' CLR		14	78%	Good	REMAIN
Live Oak	13' CLR	16' to Street	13	69%	Fair	REMAIN
Live Oak	12' CLR	14' to Street	9	81%	Good	REMAIN
Live Oak	14' CLR	18' to Street	14	66%	Fair	REMAIN
Live Oak	14' CLR	18' to Street	12	72%	Good	REMOVE
Live Oak	14' CLR	18' to Street	12	47%	Poor	REMOVE
Live Oak	12' CLR	20' to Street	11	66%	Fair	REMOVE
Live Oak	12' CLR	13' to Street	8	53%	Poor	REMOVE
Live Oak	14' CLR	14' to Street	8	56%	Fair	REMOVE
Live Oak	13' CLR	12' to Street	8	72%	Good	REMAIN
Live Oak	12' CLR	15' to Street	8	69%	Fair	REMAIN
Live Oak			5	78%	Good	REMAIN
Live Oak	14' CLR	20' to Street	14	81%	Good	REMAIN
Live Oak	14' CLR	15' to Street	12	69%	Fair	REMAIN
Live Oak	14' CLR	12' to Street	12	56%	Fair	REMAIN
Live Oak	18' CLR	13' to Street	13	63%	Fair	REMAIN
Live Oak	19' CLR	18' to Street	10	59%	Fair	REMOVE
Live Oak	15' CLR	16' to Street	11	63%	Fair	REMAIN
Live Oak	16' CLR	15' to Street	14	59%	Fair	REMOVE
Live Oak	16' CLR	14' to Street	13	69%	Fair	REMAIN
Black Olive			12	53%	Poor	REMAIN
Live Oak			8	53%	Poor	REMOVE
Black Olive			14	72%	Good	REMAIN
Sabal Palm				91%	Excellent	REMOVE
Sabal Palm				91%	Excellent	REMOVE
Sabal Palm				84%	Good	REMOVE
Sabal Palm				84%	Good	REMOVE
Sabal Palm				91%	Excellent	REMOVE
Sabal Palm				69%	Fair	REMOVE
Sabal Palm				94%	Excellent	REMOVE
Sabal Palm				84%	Good	REMOVE
Sabal Palm				91%	Excellent	REMOVE
Sabal Palm				88%	Excellent	REMOVE
Mahogany			4	53%	Poor	REMOVE
Black Olive			13	84%	Good	REMOVE
Black Olive			15	69%	Fair	REMOVE
Black Olive			17	78%	Good	REMOVE
Live Oak	18" CLR	27' to Street	19	81%	Good	REMOVE
Live Oak	18' CLR	24' to Street	18	66%	Fair	REMOVE
Live Oak	13' CLR	22' to Street	15	72%	Good	REMOVE
Live Oak	13' CLR	31' to Street	22	81%	Good	REMAIN
Live Oak	14' CLR	24' to Street	21	81%	Good	REMAIN